





x1










## DHESIVE MOUNT FE



















# (8)CONNECT

- 1 Remove J605 connector
- Connect splitter to J605 (Audio Video board)
- 3 Connect splitter to J4 (PinSound board)
- 4 Connect back J605 to splitter



## 9 CONNECT

- 1 Remove J138 connector
- Connect splitter to J138 (Driver board)
- (3) Connect splitter to J3 (PinSound board)
- (4) Connect back J138 to splitter (use Z-connector if needed)




### (10)CONNECT

Audio Video Board J504 +J505 (Speakers)

PinSound Board J504 WPC-95 + J505 WPC-95 (Speakers)

J504 WPC-95 5 WPC-95



(11)LOAD USB

# NEED HELP?

www.pinsound.org/help